

Well Name : Wright 33-5 21-1

API # : 007-06276




Photo 1: Wellhead sign.



Photo 2: Wellhead sign.

Well Name : Wright 33-5 21-1
API # : 007-06276



Photo 3: Soil separation at SE corner slope.



Photo 4: Soil separation at SE corner.

Well Name : Wright 33-5 21-1
API # : 007-06276



Photo 5: Soil separation at SE corner.



Photo 6: Soil separation at SE corner.

Well Name : Wright 33-5 21-1
API # : 007-06276



Photo 7: Erosion channel on E perimeter looking down slope.



Photo 8: Erosion channel on E perimeter looking up slope.

Well Name : Wright 33-5 21-1
API # : 007-06276



Photo 9: Check dam and waddle breach in NE corner.



Photo 10: Waddle failing due to sediment filling up backside allowing stormwater and sediment to flow onto location.