

Inspection Photos

API: 05-067-09367

Operator: Hilcorp Energy Company

Inspection Number: 680602491

Inspection Date: 2/5/2018



Photo 1. View of the project area from the northwestern corner facing center.



Photo 2. View of the western portion of the project area from the northwestern corner facing southward. Revegetation is progressing with grasses such as smooth brome (*Bromus inermis*), intermediate wheatgrass (*Thinopyron intermedium*), and dropseed (*Sporobolus* sp.).



Photo 3. View of the eastern edge of the working area from the northeastern corner facing southward.



Photo 4. View of stormwater controls south of the access entrance. Appear to be functioning.



Photo 5. View of erosional channel forming in the northeastern portion of the project area.



Photo 6. View of wattles on the south side of the access near the well pad entrance that need maintenance/replacement.