

Inspection Photos

API: 05-067-06381

Operator: BP AMERICA PRODUCTION COMPANY

Inspection Number: 680602489

Inspection Date: 2/5/2018



Photo 1. View of the project area from the northwestern corner facing center. Well pad and access are recontoured, appear to be seeded, and is mulched with straw mulch. Germination, weeds, stormwater, and vegetation establishment will continue to need monitoring.



Photo 2. View of the western portion of the project area from the northwestern corner facing eastward.



Photo 3. View of the northern edge of the working area from the northwestern corner facing eastward.



Photo 4. View of the eastern portion of the project area from the northeastern corner facing southward. Stormwater erosion appears to be controlled at this time.



Photo 5. View of riser southeast of the project area that is still in place.