

Well Name : Marquez A2  
API # : 007-06327




Photo 1: Wellhead sign at turn off from CR.



Photo 2: Erosion control waddle in SW corner not trenched in, not back filled, and improperly staked.

Well Name : Marquez A2  
API # : 007-06327



Photo 3: S perimeter looking E. Erosion control waddle and top soil pile along S perimeter. Waddle improperly installed.



Photo 4: Sign marking top soil pile.

Well Name : Marquez A2  
API # : 007-06327



Photo 5: S perimeter looking NW.  
Waddles, berm, and edge of gravel not yet to base of berm.



Photo 6: Additional top soil pile in SE corner with waddles and sign. Waddles improperly installed.

Well Name : Marquez A2

API # : 007-06327



Photo 7: E perimeter looking N. Berm and erosion control waddles. Waddles improperly installed.



Photo 8: E perimeter with erosion control waddle line ending short of NE corner.

Well Name : Marquez A2  
API # : 007-06327



Photo 9: N perimeter looking NW. Berm and no erosion control waddle line. Single erosion control waddle check dam.



Photo 10: Check dam on N perimeter. Waddle improperly installed.

Well Name : Marquez A2  
API # : 007-06327



Photo 11: N perimeter approaching top of cut slope. Ditch and berm. No velocity control BMPs installed in ditch.



Photo 12: Top of cut slope looking S. Ditch and berm. No erosion control waddle line and no velocity control BMPs installed in ditch.

Well Name : Marquez A2  
API # : 007-06327



Photo 13: Cattle guard installed at entrance.



Photo 14: W perimeter looking N.