

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/14/2017

Submitted Date:

02/16/2018

Document Number:

688000133**FIELD INSPECTION FORM**Loc ID 312314 Inspector Name: YOUNG, ROB On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 31257Name of Operator: FRITZLER RESOURCES INCAddress: P O BOX 114City: FORT MORGAN State: CO Zip: 80701**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**3 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Axelson, John		john.axelson@state.co.us	
Fritzler, Gene	970-768-0845	gfritzler@bresnan.net	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
221192	WELL	PR	02/10/2006	OW	075-09318	FEHRINGER 1	PR
272486	PIT	AC			-	FEHRINGER #1	EI

**General Comment:**

Environmental inspection. Requesting eForm 27 for the closure of the unused steel partially buried produced water vessel.

**Location**Overall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: Overall Good: ☐**Spills:**

Type	Area	Volume		

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1		BV STEEL		,	
Comment:	Unused steel partially buried oil skim tank. Active partially buried fiberglass oil skim tank.					
Corrective Action:	Submit a eForm 27 for prior approval detailing the removal of the unused oil skim tank.				Date:	03/02/2018

**Paint**

Condition	<input type="text"/>	
Other (Content)	<input type="text"/>	
Other (Capacity)	<input type="text"/>	
Other (Type)	<input type="text"/>	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:	<input type="text"/>			
Corrective Action:	<input type="text"/>			Date: <input type="text"/>

**Venting:**

Yes/No	<input type="text"/>	
Comment:	<input type="text"/>	
Corrective Action:	<input type="text"/>	Date: <input type="text"/>

**Flaring:**

Type	<input type="text"/>	
Comment:	<input type="text"/>	
Corrective Action:	<input type="text"/>	Date: <input type="text"/>

Inspected Facilities									
Facility ID:	221192	Type:	WELL	API Number:	075-09318	Status:	PR	Insp. Status:	PR
Facility ID:	272486	Type:	PIT	API Number:	-	Status:	AC	Insp. Status:	EI

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PITType: Produced WaterLined: NOPit ID: 272486Lat: 40.991755Long: -103.181443Reference Point: SEOther: Length: 80Width: 45**Lining:**

Liner Type:

Liner Condition:

Comment: Crude oil ring has been removed per CA on FIR 680302755.

Corrective Action

Date: c**Fencing:**

Fencing Type:

Fencing Condition:

Comment: 

Corrective Action

Date: **Netting:**

Netting Type:

Netting Condition:

Comment: 

Corrective Action

Date: 

Anchor Trench Present:

Oil Accumulation:

2+ feet Freeboard:

Comment: 

Corrective Action

Date: **Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
688000134	Location photographs	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4384103">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4384103</a>