

Inspected Facilities

Facility ID: 440823 Type: LOCATION API Number: - Status: AC Insp. Status: EI

Facility ID: 454117 Type: SPILL OR API Number: - Status: AC Insp. Status: EI

Environmental

Spill/Remediation:

Comment: COGCC Environmental inspection of release from 3" diameter water line entering State Antelope T-1 pad from pad to east. Bonanza personnel indicated that release occurred at 90 elbow from internal corrosion or erosion (root cause is pending). Small excavation present at release point. Initial soil sample results are pending. Operator will provide root cause and corrective action along with confirmation soil sample results via Form 19 Supplemental Report. Photo attached.

Corrective Action: Date:

Emission Control Burner (ECB):

Comment:

Pilot: Wildlife Protection Devices (fired vessels):

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
679700813	Excavation showing failure point at elbow	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4385677