

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/15/2018

Submitted Date:

02/19/2018

Document Number:

690100389**FIELD INSPECTION FORM**Loc ID 328798 Inspector Name: Maclaren, Joe On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 10459Name of Operator: EXTRACTION OIL & GAS INCAddress: 370 17TH STREET SUITE 5300City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**4 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Carlisle, Josh		jcarlisle@extractionog.com	
,		COGCCInspections@extractionog.com	
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
248644	WELL	SI	06/01/2017	GW	123-16445	KAMMERZELL K 4-12	EG

**General Comment:**

Engineering Integrity Inspection performed on February 15th, 2018 in response to initial form 19 spill report Doc #401544246 received by COGCC on 02/13/2018 that outlines: While removing a partially buried produced water vessel at the Kammerzell 15-16, historic suspected soil impacts were observed. The details of observations made during this field inspection are available in the flowline section of this report. Photos uploaded can be accessed via link(s) at end of report.

**Inspected Facilities**

Facility ID: 248644 Type: WELL API Number: 123-16445 Status: SI Insp. Status: EG

**Idle Well**

Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: This well has been Temporarily Abandoned - flowlines/ equipment removed.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**Flowline**

#1	Type:	of Lines
----	-------	----------

**Flowline Description**

Flowline Type: \_\_\_\_\_ Size: \_\_\_\_\_ Material: \_\_\_\_\_

Variance: \_\_\_\_\_ Age: \_\_\_\_\_ Contents: \_\_\_\_\_

**Integrity Summary**

Failures: \_\_\_\_\_ Spills: \_\_\_\_\_ Repairs Made: \_\_\_\_\_

Coatings: \_\_\_\_\_ H2S: \_\_\_\_\_ Cathodic Protection: \_\_\_\_\_

**Pressure Testing**

Witnessed: \_\_\_\_\_ Test Result: \_\_\_\_\_ Charted: \_\_\_\_\_

**COGCC Rules(check all that apply)**

☐ 1101. Installation and Reclamation ☐ 1102. Operations, Maintenance, and Repair ☒ 1103. Abandonment

Comment: COGCC Inspector spoke with Extraction Oil & Gas contract personnel (with Laser Oilfield Services) on location. The production equipment/ tanks at battery have been removed (battery also serviced Kammerzell K15-16/ API 123-16471) . All flowlines associated with this well have been removed; including the wellhead flowline, dump flowlines and process piping. There was a historically abandoned wellhead flowline (2" Carbon Steel) encountered while excavating - this flowline has also been removed.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**COGCC Comments**

Comment	User	Date
<u>Note: There is a disconnected/ out of service gas gathering riser and meter run on the west end of the facility location.</u>	maclarej	02/19/2018
<u>COGCC Rule 1004. FINAL RECLAMATION OF WELL SITES AND ASSOCIATED PRODUCTION FACILITIES (partial description of rule) a. Well sites and associated production facilities. Upon the plugging and abandonment of a well, all pits, mouse and rat holes and cellars shall be backfilled. All debris, abandoned gathering line risers and flowline risers, and surface equipment shall be removed within three (3) months of plugging a well.</u>		

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401548898	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4381177">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4381177</a>
690100391	Excavation and remediation activities	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4381174">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4381174</a>
690100392	Wellhead temporarily abandoned	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4381175">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4381175</a>
690100393	Disconnected meter run	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4381176">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4381176</a>

