

Location Name: MUSF #2 Well COGCC WW# 454138 Inspection Date: 2/23/18



Location Name: MUSF #2 Well COGCC WW# 454138 Inspection Date: 2/23/18



Spill area below excavation



Location Name: MUSF #2 Well COGCC WW# 123456 Inspection Date: 2/23/18



Spill area



Location Name: MUSF #2 Well COGCC WW# 123456 Inspection Date: 2/23/18



From spill area looking down flow line to toward tank battery.



Location Name: MUSF #2 Well COGCC WW# 123456 Inspection Date: 2/23/18



Pipeline excavation. Pipeline on top is source of leak.



Location Name: MUSF #2 Well COGCC WW# 454138 Inspection Date: 2/23/18



Pipeline excavation. Pipeline on top is source of leak.



Location Name: MUSF #2 Well COGCC WW# 454138 Inspection Date: 2/23/18



02.23.2018 12:22

Pipeline excavation and spill area.



Location Name: MUSF #2 Well COGCC WW# 454138 Inspection Date: 2/23/18



Pipeline excavation. Pipeline flows toward tank battery visible in background of photo.

