

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:  
401460412  
Date Received:  
11/15/2017

FIR RESOLUTION FORM

CA Summary:  
2 of 2 CAs from the FIR responded to on this Form  
2 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10000  
Name of Operator: BP AMERICA PRODUCTION COMPANY  
Address: 380 AIRPORT RD  
City: DURANGO State: CO Zip: 81303  
Contact Name and Telephone:  
Name:  
Phone: ( ) Fax: ( )  
Email:

Additional Operator Contact:

Contact Name	Phone	Email
Beebe, Sabre		Sabre.Beebe@bp.com
.		SanJuanCOGCC@bp.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 680602001  
Inspection Date: 08/30/2017 FIR Submit Date: 09/13/2017 FIR Status:

Inspected Operator Information:

Company Name: BP AMERICA PRODUCTION COMPANY Company Number: 10000  
Address: 380 AIRPORT RD  
City: DURANGO State: CO Zip: 81303

LOCATION - Location ID: 306800

Location Name: SOUTHERN UTE GAS UNIT Number: 13SWNE County: LA PLATA  
N-N33N8W  
Qtrqr: SWNE Sec: 13 Twp: 33N Range: 8W Meridian: N  
Latitude: 37.106915 Longitude: -107.664044

FACILITY - API Number: 05-067-00 Facility ID: 267055

Facility Name: SOUTHERN UTE N Number: 2  
Qtrqr: SWNE Sec: 13 Twp: 33N Range: 8W Meridian: N  
Latitude: 37.106915 Longitude: -107.664044

CORRECTIVE ACTIIONS:

1  CA# 101310

Corrective Action: Flowering and seeding individuals need to be removed (and properly disposed of) to prevent further seed dispersal, and additional treatments will be needed in 2018 (before flowering). Date: 10/13/2017

Response: CA COMPLETED Date of Completion: 09/22/2017

Operator Comment: FIRR #401410992 field to close out this CA

COGCC Decision: Approved pending re-inspection

COGCC  
Representative:

2  CA# 101311

Corrective Action: Stormwater controls need to be installed to stabilize erosion within the northern project area. The eastern cut-slope needs to be monitored and revegetation/stormwater controls need to be applied if erosion worsens.

Date: 10/13/2017

Response: CA COMPLETED

Date of Completion: 10/26/2017

Operator Comment: The diversion ditch has been cleaned and re-established. Rock armour has been put into place and rock check dams have been installed to address the storm water flow coming onto and off of the well pad. See attached photos.

COGCC Decision: Approved pending re-inspection

COGCC  
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: FIRR #401410992 field to close out this CA #1  
The diversion ditch has been cleaned and re-established. Rock armour has been put into place and rock check dams have been installed to address the storm water flow coming onto and off of the well pad. See attached photos.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Sabre Beebe

Signed: \_\_\_\_\_

Title: Compliance Specialist

Date: 11/15/2017 1:23:07 PM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
401460412	FIR RESOLUTION SUBMITTED
401460447	Storm water BMP photos

Total Attach: 2 Files