

Photo 1: Wellhead sign.



Photo 2: Location overview.





Photo 3: Open top tank without signs previous inspection.



Photo 4: Open top tank with new sign.





Photo 5: Stained soil and gravel under separator for Allison Unit Com #63 previous inspection.



Photo 6: Cleaned up soil and gravel under separator for Allison Unit Com #63.





Photo 7: Unused equipment at pump jack previous inspection.



Photo 8: Removed unused equipment at pump jack.





Photo 9: Impacted soil at wellhead previous inspection.



Photo 10: Impacted soil at wellhead current inspection.





Photo 11: Impacted soil and gravel outside compressor entry noted in previous inspection.



Photo 12: Impacted soil and gravel outside compressor entry way.





Photo 13: Rust streaked open top tank previous inspection.



Photo 14: Open top tank.





Photo 15: Dried thistle along well access road.



Photo 16: Dried thistle in S perimeter.

