

# Construction and Stormwater Inspection

February 27, 2018

Operator: ENERPLUS RESOURCES (USA) CORPORATION - #10177

Location ID: 450827

Inspection Document #: 682403339

Weld County, CO

SWSE Section 26 T8N R67W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos  
Location Name: IRISH PAD  
Location ID: 450827



**Photo 1.** Photo taken from the entrance of location off CR 90, facing South. Photo illustrates Operator sign.



**Photo 2.** Photo taken from the northern perimeter of the location, facing South. Water truck at location to aid in construction operations and controlled fugitive dust.

Inspection Photos  
Location Name: IRISH PAD  
Location ID: 450827



**Photo 3.** Photo taken from the northwest perimeter of the location, facing West. Silt fence BMP has been installed around portions of the northern and eastern location, and the entire southern and western perimeter of the location.



**Photo 4.** Photo taken from the northwest perimeter of the location, facing South. See comments under Photo 3.

Inspection Photos  
Location Name: IRISH PAD  
Location ID: 450827



**Photo 5.** Photo taken from the southwest perimeter of the location, facing East. See comments under Photo 3.



**Photo 6.** Photo taken from the southern perimeter of the location, facing East. Silt fence BMP has been damaged from topsoil storage operations. Operator representative at location indicated the BMP was scheduled to be fixed sometime on February 27, 2018.

Inspection Photos  
Location Name: IRISH PAD  
Location ID: 450827



**Photo 7.** Photo taken from the southern location on the topsoil stockpile, facing West. Appears the Operator is still in-process of salvaging topsoil. Topsoil is being stored along the eastern and southern perimeter of the location.



**Photo 8.** Photo taken from the southern location on the topsoil stockpile, facing East. See comments under Photo 7.

Inspection Photos  
Location Name: IRISH PAD  
Location ID: 450827



**Photo 9.** Photo taken from the southeast perimeter of the location, facing North. See comments under Photo 3.



**Photo 10.** Photo taken from the eastern perimeter of the location, facing North. Silt fence BMP stops before the end of the topsoil stockpile. Operator shall install BMPs around all topsoil stockpiles. Operator representative at location indicated a BMP would be installed around the topsoil stockpile but did not provide a date.