

# Interim Reclamation and Stormwater Inspection

February 27, 2018

Operator: ENERPLUS RESOURCES (USA) CORPORATION - #10177

Location ID: 449800

Inspection Document #: 682403344

Weld County, CO

SESW Section 36 T8N R67W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos  
Location Name: MAPLE #8-67-36-25C  
Location ID: 449800



**Photo 1.** Photo taken from the entrance of the location off the intersection of CR 25 & CR 86. Photo illustrates Operator sign.



**Photo 2.** Photo taken from the entrance of the location off the intersection of CR 25 & CR 86, facing West. Operator has installed a tracking pad device. Appears maintenance may be needed for the tracking pad.

Inspection Photos  
Location Name: MAPLE #8-67-36-25C  
Location ID: 449800



**Photo 3.** Photo taken of another tracking pad device along the eastern main access road, facing North. Tracking pad device appears to be proper functioning condition.



**Photo 4.** Photo taken from the tracking pad device at the entrance of the well pad location, facing West. Appears maintenance is required as sediment has accumulated in the tracking pad device and is no longer properly functioning.

Inspection Photos  
Location Name: MAPLE #8-67-36-25C  
Location ID: 449800



**Photo 5.** Photo taken near the entrance of the well pad location, facing South. Operator has a trash bin at location which is not covered- see Photo 6.



**Photo 6.** Photo taken from the trash bin. Operator shall cover trash bin to prevent trash from blowing off location.

Inspection Photos  
Location Name: MAPLE #8-67-36-25C  
Location ID: 449800



**Photo 7.** Photo taken from the western perimeter of the location, facing South. Operator has failed to perform interim reclamation to reduce areas not needed for production operations per Rule 1003.

Inspection Photos

Location Name: MAPLE #8-67-36-25C

Location ID: 449800



**Photo 8.** Photo taken from the western perimeter of the location, facing East. See comments under Photo 7.

Inspection Photos  
Location Name: MAPLE #8-67-36-25C  
Location ID: 449800



**Photo 9.** Photo taken from the western perimeter of the location, facing North. See comments under Photo 7.

Inspection Photos

Location Name: MAPLE #8-67-36-25C

Location ID: 449800



**Photo 10.** Photo taken from the western perimeter of the location, facing North. Topsoil stockpile appears to be in compliance with Rule 1002.c.

Inspection Photos  
Location Name: MAPLE #8-67-36-25C  
Location ID: 449800



**Photo 11.** Photo taken from the northeast sediment trap, facing East. Sediment trap appears to be in proper functioning condition. No sediment discharge from location was observed.



**Photo 12.** Photo taken from the southeast sediment trap, facing West. See comments under Photo 11.