

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/28/2018

Submitted Date:

02/28/2018

Document Number:

684905088**FIELD INSPECTION FORM**Loc ID 444819 Inspector Name: Pesicka, Conor On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10542Name of Operator: CUB CREEK ENERGYAddress: 200 PLAZA DRIVE SUITE 100City: HIGHLANDS State: CO Zip: 80129**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:2 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Adamczyk, Megan		megan.adamczyk@state.co.us	
Gomez, Jason		jason.gomez@state.co.us	
Baily, Scott		scott.baily@cub-creek.com	
Leonard, Mike		mike.leonard@state.co.us	
Berberick, Dan		dan.berberick@cub-creek.com	
Corey, Alex		alex.corey@cub-creek.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
444817	WELL	DG	07/20/2017		123-42767	Litzenberger 16	DG

General Comment:

LocationOverall Good: ☒**Signs/Marker:**

Type	DRILLING/RECOMP		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:		Date: _____
Corrective Action:		

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

Type	LOCATION		
Comment:	Sound walls		
Corrective Action:		Date:	

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 444817 Type: WELL API Number: 123-42767 Status: DG Insp. Status: DG**Complaint**Comment: [Complaint #: 200445375, 200445376](#)[Field Inspector Assigned: C Pesicka](#)[Well Number: 05- Location #: 444819](#)[Inspection Document #: 684905088](#)[Nature of complaint: Sound](#)[If Sound GPS Coordinates of Survey Location: n/a](#)[Inspection Observations:](#)[An inspection of the above site was conducted with a focus on sound. The site is down, as the frac fleet is being exchanged for a quiet fleet. Additional sound mitigation has been placed around the location and along the access road.](#)[18A doc#: # 200445380, 200445381](#)

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass	Vehicle Tracking	Pass	

Comment:

Corrective Action:

Date:

Pits: ☐ NO SURFACE INDICATION OF PIT