

Inspection Photos

02/26/2018

Operator: WESTERN OPERATING COMPANY -
95620

Location ID: 312291

Inspection Doc. Number: 682503173

Logan County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC

Inspection Photos
Operator: WESTERN OPERATING COMPANY - 95620
Location ID: 312291



Photo 1: Photo taken from the east end of the location, facing south. The following photos show areas of erosion degradation, where erosion has not been repaired and no stabilization and stormwater BMPs have been installed or maintained per corrective actions. Additionally, photos show no remediation/reclamation activities appear to have been conducted per corrective actions.



Photo 2: Photo taken from the east end of the location, facing southeast. See comments under photo 1.

Inspection Photos
Operator: WESTERN OPERATING COMPANY - 95620
Location ID: 312291



Photo 3: Photo taken from the east end of the location, facing east. See comments under photo 1. 6 foot measuring stick for reference.



Photo 4: Photo taken from the east of the location, facing west. See comments under photo 1. 6 foot measuring stick for reference.

Inspection Photos
Operator: WESTERN OPERATING COMPANY - 95620
Location ID: 312291



Photo 5: Photo taken from the east of the location, facing southeast. See comments under photo 1. 6 foot measuring stick for reference.



Photo 6: Photo taken from the east of the location, facing west. See comments under photo 1. 6 foot measuring stick for reference.

Inspection Photos
Operator: WESTERN OPERATING COMPANY - 95620
Location ID: 312291



Photo 7: Photo taken from the southeast of the location, facing northwest. See comments under photo 1. 6



Photo 8: Photo taken from the east of the location, facing northwest. See comments under photo 1.

Inspection Photos
Operator: WESTERN OPERATING COMPANY - 95620
Location ID: 312291



Photo 9: Photo taken from the southeast of the location, facing northwest. See comments under photo 1.



Photo 10: Photo taken from the southeast of the location, facing north. See comments under photo 1.

Inspection Photos
Operator: WESTERN OPERATING COMPANY - 95620
Location ID: 312291



Photo 11: Photo taken from the southeast of the location, facing northwest. See comments under photo 1.



Photo 12: Photo taken from the south end of the location, facing northwest. See comments under photo 1.

Inspection Photos
Operator: WESTERN OPERATING COMPANY - 95620
Location ID: 312291



Photo 13: Photo taken from the southwest of the location. Photo shows areas where sediment deposition from sediment laden stormwater runoff from the location has degraded the vegetation in the adjacent areas.



Photo 14: See comments under photo 13. 6 foot measuring stick for reference.

Inspection Photos
Operator: WESTERN OPERATING COMPANY - 95620
Location ID: 312291



Photo 15: Photo taken from the southwest end of the location, facing northeast. See comments under photo 1.



Photo 16: Photo taken from the southwest end of the location. Photo shows stormwater erosion degradation on the adjacent areas due to stormwater runoff from the location. See comments under photo 1.

Inspection Photos
Operator: WESTERN OPERATING COMPANY - 95620
Location ID: 312291



Photo 17: Photo taken from the west end of the pit, facing east. Photo shows stormwater runoff has caused erosion degradation at the pit walls, which has then contributed to degraded to the adjacent areas.



Photo 18: See comments under photo 17. 6 foot measuring stick for reference

Inspection Photos
Operator: WESTERN OPERATING COMPANY - 95620
Location ID: 312291



Photo 19: Photo taken from the west end of the location, facing west. Photo shows gully erosion due to stormwater erosion from the location has not been repaired, stabilized or reclaimed. No stabilization and stormwater BMPs have been installed or maintained. 6 foot measuring stick for reference.



Photo 20: Photo taken from the west end of the location, facing east. See comment under photo 19.