

FORM
INSPRev
X/15

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/02/2018

Submitted Date:

03/05/2018

Document Number:

674902085

FIELD INSPECTION FORM

Loc ID _____ Inspector Name: _____ On-Site Inspection
326264 _____ Hughes, Jim _____ 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10663
 Name of Operator: ENDURING RESOURCES LLC
 Address: 511 16TH STREET #700
 City: DENVER State: CO Zip: 80202

Findings:

10 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Fischer, Alex		alex.fischer@state.co.us	
McDaniel, James	505-444-3004	jmcdaniel@enduringresources.com	SW Inspection Reports
Pohl, April	505-636-9722	apohl@enduringresources.com	SW Inspection Reports

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
216136	WELL	PR	03/08/2002	GW	067-07742	CHANEY 1-1	EI

General Comment:

On March 3, 2018 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Enduring Resources Chaney #1-1. For the most recent field inspection report of this facility, please refer to document #680601419.

Location

Lease Road:			
Type	Access		
comment:			
Corrective Action			Date:

Overall Good:

Signs/Marker:			
Type	WELLHEAD		
Comment:	Free standing sign near location entrance.		
Corrective Action:			Date:

Emergency Contact Number:			
Comment:	Posted on location sign.		
Corrective Action:			Date: _____

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:			
Type	LOCATION		
Comment:	Perimeter chain link fencing around location.		
Corrective Action:			Date:

Equipment:			corrective date
Type: Ancillary equipment	# 1		
Comment:	Generator.		
Corrective Action:			Date:
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:			Date:
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:			Date:
Type: Pig Station	# 1		
Comment:			
Corrective Action:			Date:

Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:			Date:
Type: Ancillary equipment	# 1		
Comment:	Chemical injection system.		
Corrective Action:			Date:
Type: Pump Jack	# 1		
Comment:			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLs	PBV STEEL		37.232259,-107.800545
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)	95 bbl.	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				
				Date:

Venting:

Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 216136 Type: WELL API Number: 067-07742 Status: PR Insp. Status: EI

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Waddles	Pass					
Rip Rap	Pass	Compaction	Pass	Material Handling And Spill Prevention	Pass	

Comment: [Drip pot on load out line for produced water vessel. Secondary containment for chemical injection system and lube oil container.](#)

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
On March 3, 2018 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Enduring Resources Chaney #1-1. For the most recent field inspection report of this facility, please refer to document #680601419. Rip rap and wattles have been installed along the eastern edge of the location since the last inspection.	hughesj	03/05/2018

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
674902086	Inspection Photos 3.2.18	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4394049