

Inspection Photos
Location Name: WGR Hallmark #1-32
API: 05-067-08004



Access road photo from location looking south.



Woody debris in SW corner of location.

Inspection Photos
Location Name: WGR Hallmark #1-32
API: 05-067-08004



Rilling on cut slope along western edge of location.



Wind-rowed soil in NW corner of location.

Inspection Photos
Location Name: WGR Hallmark #1-32
API: 05-067-08004



Alternate view of soil in NW corner.



Soil in wind rows does not appear to be impacted material.

Inspection Photos
Location Name: WGR Hallmark #1-32
API: 05-067-08004



Light tan soil in wind rows.



Ground level in northwest corner of location is lower than the rest of the pad.

Inspection Photos
Location Name: WGR Hallmark #1-32
API: 05-067-08004



Woody debris on east side of "pit area".



Cut slope on west side of "pit area".