

# Construction and Stormwater Inspection

February 14, 2018

Operator: EXTRACTION OIL & GAS INC - #10459

Location ID: 452694

Inspection Document #: 682403354

Weld County, CO

NESE Section 7 T4N R68W


Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos  
Location Name: Trott /7-L  
Location ID: 452694



**Photo 1.** Photo taken from the entrance of location, facing West. Operator has installed tracking device BMPs.



**Photo 2.** Photo taken from the entrance of location, facing North. Operator has installed a culvert along the roadside ditch.

Inspection Photos  
Location Name: Trott /7-L  
Location ID: 452694




**Photo 3.** Photo taken from the entrance of the well location, facing East. Operator has installed sound walls along the access road, east and south well location perimeter, and a portion of the north and west well location perimeter.



**Photo 4.** Photo taken from the entrance of the well location, facing South. Operator has installed a ditch BMP along the well location perimeter which is directed to retention areas.

Inspection Photos  
Location Name: Trott /7-L  
Location ID: 452694



**Photo 5.** Photo taken from the southeastern well location, facing South. See comments under Photo 4.



**Photo 6.** Photo taken from the southeast location perimeter, facing South. Operator has installed a stabilized outlet (spillway) along the outer perimeter ditch. It should be noted blankets used for a stabilized outlet would only be considered a temporary BMP. If the stabilized outlet is intended to be a permanent BMP, more appropriate material should be installed (i.e., riprap).

Inspection Photos  
Location Name: Trott /7-L  
Location ID: 452694



**Photo 7.** Photo taken from the southeast location, facing West. Operator has installed a retention area in conjunction to the well pad ditches.



**Photo 8.** Photo taken from the southeast location, facing West. See comments under Photo 6 regarding the stabilized outlet (spillway).

Inspection Photos  
Location Name: Trott /7-L  
Location ID: 452694



**Photo 9.** Photo taken from the southwest location, facing East. Appears topsoil has been salvaged and stored along the southern and western perimeter of the location.



**Photo 10.** Photo taken from the southwest location, facing North. See comments under Photo 9.

Inspection Photos  
Location Name: Trott /7-L  
Location ID: 452694



**Photo 11.** Photo taken from the northwest location, facing South. See comments under Photo 9.



**Photo 12.** Photo taken from the northwest location, facing East. See comments under Photo 4.

Inspection Photos  
Location Name: Trott /7-L  
Location ID: 452694



**Photo 13.** Photo taken from the northeast location, facing West. See comments under Photo 4.



**Photo 14.** Photo taken from the northeast location, facing South. See comments under Photo 4.

Inspection Photos  
Location Name: Trott /7-L  
Location ID: 449583



**Photo 15.** Photo taken from the eastern, facing North. See comments under Photo 6 regarding the stabilized outlet (spillway).