

FORM  
INSPRev  
X/15

**State of Colorado**  
**Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/28/2018

Submitted Date:

02/28/2018

Document Number:

690001180**FIELD INSPECTION FORM**

Loc ID 332982 Inspector Name: Carlile, Craig On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Operator Information:**OGCC Operator Number: 100322Name of Operator: NOBLE ENERGY INCAddress: 1001 NOBLE ENERGY WAYCity: HOUSTON State: TX Zip: 77070**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION  
 FOLLOW UP INSPECTION REQUIRED  
 NO FOLLOW UP INSPECTION REQUIRED

**Findings:**5 Number of Comments0 Number of Corrective Actions Corrective Action Response Requested**Contact Information:**

| Contact Name | Phone | Email                                  | Comment |
|--------------|-------|--|---------|
|              |       | NBL_DJBU_Inspections@NB<br>LENERGY.COM |         |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name   | Insp Status |
|-------------|------|--------|-------------|------------|-----------|-----------------|-------------|
| 260681      | WELL | SI     | 05/01/2017  | GW         | 123-20531 | BB DRAW H 4-6JI | SI          |

**General Comment:**

**Location**

Overall Good:

**Signs/Marker:**

|                    |          |       |  |
|--------------------|----------|-------|--|
| Type               | WELLHEAD |       |  |
| Comment:           |          |       |  |
| Corrective Action: |          | Date: |  |

Emergency Contact Number:

|                    |  |       |  |
|--------------------|--|-------|--|
| Comment:           |  | Date: |  |
| Corrective Action: |  |       |  |

Overall Good:

**Spills:**

| Type | Area | Volume |  |  |
|------|------|--------|--|--|
|------|------|--------|--|--|

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

|                    |          |       |  |
|--------------------|----------|-------|--|
| Type               | WELLHEAD |       |  |
| Comment:           | Pipe     |       |  |
| Corrective Action: |          | Date: |  |

**Equipment:**

|                    |     |       |                 |
|--------------------|-----|-------|-----------------|
| Type: Plunger Lift | # 1 |       | corrective date |
| Comment:           |     |       |                 |
| Corrective Action: |     | Date: |                 |

**Tanks and Berms:**

| Contents           | # | Capacity | Type         | Tank ID | SE GPS |
|--------------------|---|----------|--------------|---------|--------|
| PRODUCED WATER     | 2 | OTHER    | PBV CONCRETE |         | ,      |
| Comment:           |   |          |              |         |        |
| Corrective Action: |   |          |              | Date:   |        |

**Paint**

|                  |        |
|------------------|--------|
| Condition        |        |
| Other (Content)  |        |
| Other (Capacity) | 60 Bbl |
| Other (Type)     |        |

**Berms**

| Type               | Capacity                    | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|-----------------------------|---------------------|---------------------|-------------|
|                    |                             |                     |                     |             |
| Comment:           | Shared with crude oil tank. |                     |                     |             |
| Corrective Action: |                             |                     | Date:               |             |

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|----------|---|----------|------|---------|--------|
|----------|---|----------|------|---------|--------|

|                    |          |                     |                     |             |                       |
|--------------------|----------|---------------------|---------------------|-------------|-----------------------|
| CRUDE OIL          | 2        | 300 BBLs            | STEEL AST           |             | 40.257790,-104.667840 |
| Comment:           |          |                     |                     |             |                       |
| Corrective Action: |          |                     |                     |             | Date:                 |
| <b>Paint</b>       |          |                     |                     |             |                       |
| Condition          |          |                     |                     |             |                       |
| Other (Content)    |          |                     |                     |             |                       |
| Other (Capacity)   |          |                     |                     |             |                       |
| Other (Type)       |          |                     |                     |             |                       |
| <b>Berms</b>       |          |                     |                     |             |                       |
| Type               | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |                       |
| Earth              | Adequate | Walls Sufficient    | Base Sufficient     | Adequate    |                       |
| Comment:           |          |                     |                     |             |                       |
| Corrective Action: |          |                     |                     |             | Date:                 |
| <b>Venting:</b>    |          |                     |                     |             |                       |
| Yes/No             | NO       |                     |                     |             |                       |
| Comment:           |          |                     |                     |             |                       |
| Corrective Action: |          |                     |                     |             | Date:                 |
| <b>Flaring:</b>    |          |                     |                     |             |                       |
| Type               |          |                     |                     |             |                       |
| Comment:           |          |                     |                     |             |                       |
| Corrective Action: |          |                     |                     |             | Date:                 |

**Inspected Facilities**

Facility ID: 260681 Type: WELL API Number: 123-20531 Status: SI Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: Shut in at separator.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**BradenHead**

Comment: Bradenhead plumbed to surface.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**Reclamation - Storm Water - Pit**

**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Gravel           | Pass            |                         |                       |               |                          |         |

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**COGCC Comments**

| Comment                             | User     | Date       |
|-------------------------------------|----------|------------|
| <a href="#">Routine inspection.</a> | carlilec | 02/28/2018 |

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description          | URL   |
|--------------|----------------------|---|
| 401558458    | INSPECTION SUBMITTED | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4389453">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4389453</a> |
| 690001182    | Photos               | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4389446">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4389446</a> |