


11306033

FIELD INSPECTION SHEET

Operator Mexxon O&G Corp.
 Well Name & # 1 Hamm Canyon 14-26
 Lease # COC 20434
 OIL GAS CO₂ WC DEV
 Formation Hamm Canyon Field
 Pool _____
 Circulation Medium Mud Gas Air
 Road Length _____
 Width _____ Cut _____
 NEW _____ REHAB _____ W/W P/L _____
 New Road on Lease Length _____
 New Road off lease R/W Length _____
 Existing Road R/W Needed _____
 Length _____
 Inspected P/L on Lease: Yes No
 Length _____ Width _____
 Surface _____ Underground
 Inspected off Lease/Unit Pipeline:
 Yes _____ No _____
 Length _____ Width _____
 * Surface Ownership BLM
 Topography slope below mesas
 Arroyo/wash _____ Base of Cliff _____
 Bench _____ Canyon rim _____ Mesa _____
 Cliff/scarp _____ Valley bottom _____
 Hill top slope low rise
 Plain/flat _____ Ridge _____ Saddle _____
 Terrace _____
 Existing Vegetation sage, native
grasses, rabbit brush
 Soil Rocky _____ Gravelly _____
 Sandy _____ Clayey _____
 Other _____
 Slope _____
 Drainage generally to the west
 Land Use _____
 Special Stipulations
Excess equipment and trash
around wellhead needs to
be removed
55 gal drums - unlabeled
Access road was very recently bladed
old style meter chart
Treat weeds around facilities
Next to house - oil in unlined pit
Fencing ok. Berms ok.
Health/Safety ok.
Erosion control ok.

Paint facilities

Date 05/26/05
 Inspector LUCAS VARGO
 EA # COC 20434
 County, State San Miguel CO
 Location NWSW
 S. 26 T. 4S N., R. 18 W.
 Location Moved? Yes _____ No _____
 From: _____ To: _____
 Laydown _____ Pit _____
 Pad Size 1/3 of drilling
 Paint Color Tan Seed _____
 Start Date _____ Drill Time _____
 Cut _____ Direction _____
 Fill _____ Direction _____
 Water Source _____
 Dwelling _____
 Well _____
 Utility R/W _____
 Water _____
 Arch _____ Paleo _____
 RMP 1985 55 T & E _____
 SMA BLM
 Names of Individuals on Joint
 Inspection:



AFMS9
 1/1

FIELD INSPECTION SHEET

Operator Merrion O+G Corp.
 Well Name & # 1 Hamm Canyon 14-26
 Lease # _____
 OIL (GAS) CO₂ WC DEV
 Formation Hamm Canyon Field
 Pool _____
 Circulation Medium Mud Gas Air
 Road Length _____
 Width _____ Cut _____
 NEW _____ REHAB _____ W/W P/E _____
 New Road on Lease Length _____
 New Road off lease R/W Length _____
 Existing Road R/W Needed _____
 Length _____
 Inspected P/L on Lease: Yes No
 Length _____ Width _____
 Surface _____ Underground
 Inspected off Lease/Unit Pipeline:
 Yes _____ No _____
 Length _____ Width _____
 * Surface Ownership BLM
 Topography Slope below mesas
 Arroyo/wash Base of cliff
 Bench Canyon rim Mesa _____
 Cliff/scarp Valley bottom
 Hill top slope low rise _____
 Plain/flat _____ Ridge _____ Saddle _____
 Terrace _____
 Existing Vegetation Sage, native
grasses, rabbit brush
 Soil Rocky _____ Gravelly _____
 Sandy Clayey _____
 Other _____
 Slope _____
 Drainage Generally to the west
 Land Use _____
 Special Stipulations
Excess equipment and trash
around wellhead needs to
be removed.
55 gals drums - unlabeled.
Access road was very recently bladed.
old style meter chart
Treat weeds around facilities
Next to none - oil in unlined pit.
Fencing ok. Barms ok.
Health/Safety ok.
Erosion control ok.
Paint facilities

Date 05/26/05
 Inspector LUCAS JARRO
 SA # COC 20434
 County, State San Miguel CO
 Location NWSW
 S. 26 T. 45 N., R. 18 W.
 Location Moved? Yes _____ No _____
 From: _____ To: _____
 Laydown _____ Pit _____
 Pad Size 1/3 of drilling
 Paint Color Tan Seed _____
 Start Date _____ Drill Time _____
 Cut _____ Direction _____
 Fill _____ Direction _____
 Water Source _____
 Dwelling _____
 Well _____
 Utility R/W _____
 Water _____
 Arch _____ Paleo _____
 RMP 1985 SS T & E _____
 SMA BLM
 Names of Individuals on Joint
 Inspection:

