

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/07/2018

Submitted Date:

03/07/2018

Document Number:

674200505**FIELD INSPECTION FORM**

Loc ID 452048 Inspector Name: Gomez, Jason On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_

**Operator Information:**OGCC Operator Number: 10518Name of Operator: CONFLUENCE DJ LLCAddress: 1001 17TH STREET #1250City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**3 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Dickinson, Mike		mdickinson@confluencelp.com	Sr. VP of Operations

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
452352	WELL	DG	11/01/2017		123-45542	Buford 33-10-4L	PR
452354	WELL	DG	11/02/2017		123-45544	Buford 33-9-3L	PR

**General Comment:**

**Inspected Facilities**Facility ID: 452352 Type: WELL API Number: 123-45542 Status: DG Insp. Status: PR**BradenHead**

Comment: Bradenhead plumbed to surface Observed first production breadenhead test Approx 7 to 10PSIG at start of test valve opened blew down to 0PISG 0PSIG 5min 0PSIG 10 min 0PSIG 15min 0PSIG 20min 0SPSIG 30min blow down took approx 3 to 5 secounds No fluids observed

Corrective Action:

Date:

Facility ID: 452354 Type: WELL API Number: 123-45544 Status: DG Insp. Status: PR**BradenHead**

Comment: Bradenhead plumbed to surface Observed first production breadenhead test Approx 7 to 10PSIG at start of test valve opened blew down to 0PISG 0PSIG 5min 0PSIG 10 min 0PSIG 15min 0PSIG 20min 0SPSIG 30min blow down took approx 3 to 5 secounds No fluids observed

Corrective Action:

Date: