

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/28/2018

Submitted Date:

02/28/2018

Document Number:

679904070**FIELD INSPECTION FORM**Loc ID 304383 Inspector Name: Welsh, Brian On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 10112Name of Operator: FOUNDATION ENERGY MANAGEMENT LLCAddress: 5057 KELLER SPRINGS RD STE 650City: ADDISON State: TX Zip: 75001**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**6 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

| Contact Name   | Phone                | Email                           | Comment |
|----------------|----------------------|---------------------------------|---------|
| Grant, Rachael | 918-585-1650 ext 212 | regulatory@foundationenergy.com |         |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name   | Insp Status |
|-------------|------|--------|-------------|------------|-----------|-----------------|-------------|
| 260998      | WELL | PR     | 08/08/2001  | GW         | 125-08339 | HELLING 22-7443 | PR          |

**General Comment:**[Routine Inspection](#)

**Location****Lease Road:**

|                    |                           |       |  |
|--------------------|---------------------------|-------|--|
| Type               | Access                    |       |  |
| comment:           | Trail through farm ground |       |  |
| Corrective ActionL |                           | Date: |  |

Overall Good: ☒**Signs/Marker:**

|                    |                                  |       |  |
|--------------------|----------------------------------|-------|--|
| Type               | WELLHEAD                         |       |  |
| Comment:           | Lease sign mounted to metal shed |       |  |
| Corrective Action: |                                  | Date: |  |

**Emergency Contact Number:**

|                    |  |             |
|--------------------|--|-------------|
| Comment:           |  | Date: _____ |
| Corrective Action: |  |             |

Overall Good: ☒**Spills:**

|      |      |        |  |  |
|------|------|--------|--|--|
| Type | Area | Volume |  |  |
|------|------|--------|--|--|

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

|                    |   |       |  |
|--------------------|---|-------|--|
| Type               | PUMP JACK   |       |  |
| Comment:           | Metal panels around unit, wellhead and metal shed |       |  |
| Corrective Action: |   | Date: |  |

**Venting:**

|                    |    |       |  |
|--------------------|----|-------|--|
| Yes/No             | NO |       |  |
| Comment:           |    |       |  |
| Corrective Action: |    | Date: |  |

**Flaring:**

|                    |  |       |  |
|--------------------|--|-------|--|
| Type               |  |       |  |
| Comment:           |  |       |  |
| Corrective Action: |  | Date: |  |

| Inspected Facilities |                              |       |      |             |           |         |    |               |    |
|----------------------|------------------------------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID:         | 260998                       | Type: | WELL | API Number: | 125-08339 | Status: | PR | Insp. Status: | PR |
| Producing Well       |                              |       |      |             |           |         |    |               |    |
| Comment:             | Producing. Casing Production |       |      |             |           |         |    |               |    |
| Corrective Action:   |                              |       |      | Date:       |           |         |    |               |    |

**Reclamation - Storm Water - Pit****Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Other            | Pass            | Other                   | Pass                  |               |                          |         |

Comment: [Location and access are farmed over](#)

Corrective Action:

Date: \_\_\_\_\_

**Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description          | URL   |
|--------------|----------------------|---|
| 401560526    | INSPECTION SUBMITTED | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4391221">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4391221</a> |