

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/26/2018

Submitted Date:

03/01/2018

Document Number:

688500022**FIELD INSPECTION FORM**Loc ID 319709 Inspector Name: CANFIELD, CHRIS On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10454Name of Operator: PETROSHARE CORPORATIONAddress: 9635 MAROON CIRCLE #400City: ENGLEWOOD State: CO Zip: 80112**Status Summary:**

- ☒
- THIS IS A FOLLOW UP INSPECTION
-
- ☒
- FOLLOW UP INSPECTION REQUIRED
-
- ☐
- NO FOLLOW UP INSPECTION REQUIRED

Findings:6 Number of Comments3 Number of Corrective Actions

- ☒
- Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Axelson, John		john.axelson@state.co.us	
Powell, Harold	(918)-774-3120	hpowell@petrosharecorp.com	Field Op Manager
Lloyd, Bill		blloyd@petrosharecorp.com	Operations Manager
MacLaren, Joe		joe.maclaren@state.co.us	
Brown, Devin		dbrown@petrosharecorp.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
319709	LOCATION	AC			-	STATE OF COLORADO AB-62S66W 16NESE	EI

General Comment:

Operator has moved 2 above-ground oil storage tanks, a partially-buried vessel, a horizontal separator, and other equipment approximately 1,500' to the southeast where the location is being expanded for the purpose of re-establishing the tank battery.

Location Construction

Location ID: 319709 CDP: _____

Comment: Operator has moved 2 above-ground oil storage tanks, a partially-buried vessel, a horizontal separator, and other equipment approximately 1500' to the southeast where the subject location is currently being expanded for the purpose of re-establishing the tank battery. Operator has not submitted a Form 2A Oil & Gas Location Assessment for prior approval as required by Rule 303.b.

Corrective Action: Operator must submit a Form 2A. The subject tank battery must not be put into service until a Form 2A has been approved.

Date: 03/12/2018**Form 2A COAs:****Comment:****Corrective Action:****Date:****Wildlife BMPs:****Comment:****Corrective Action:****Date:****Comment:****Corrective****Action:****Date:****On Site Inspection (305):**Surface Owner Contact Information:

Name: _____

Address: _____

Phone Number: _____

Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____

Phone Number: _____

Date Onsite Request Received: _____

Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:Summary of Operator Response to Landowner Issues:Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Environmental**Spills/Releases:**

Type of Spill: OIL

Estimated Spill Volume: _____

Comment: As of 02-26-2018, operator has not submitted a Form 19 Supplemental Report as required by Rule 906.b.(1) for Spill/Release Point ID 453361. The Form 19 Supplemental Report was due on 12-22-2018.

Corrective Action: Submit both a Form 27 Site Investigation & Remediation Work Plan and a Form 19 Supplemental Report. Form 19 Supplemental Report should, in addition to providing all required information, request closure of the spill report as work will proceed under the related Form 27 once it has been approved.

Date: 03/12/2018

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well Complaint:

DWR Receipt Num: _____ Owner Name: _____ GPS : _____ Lat _____ Long _____

Field Parameters:

Sample Location: _____ Comment: _____

Spill/Remediation:

Comment: Operator removed a partially-buried produced water vessel without prior approval of a Form 27 as required by Rule 905.b. Numerous spoil piles of contaminated soil were observed (see photo log) without appropriate storm water BMP's.

Corrective Action: Operator must submit a Form 27 providing a detailed plan to investigate site of the above-mentioned vessel.
Implement storm water BMP's.

Date: 03/12/2018

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

COGCC Comments

Comment	User	Date
	canfielc	03/01/2018

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/webblink/>) and search by document number:

Document Num	Description	URL
401559687	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4390454
688500023	Photo Log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4390453