

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/01/2018

Submitted Date:

03/01/2018

Document Number:

690001189

FIELD INSPECTION FORM

Loc ID 331872 Inspector Name: Carlile, Craig On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 36200
 Name of Operator: GRYNBERG* JACK DBA GRYNBERG PETROLEUM CO
 Address: 3600 S. YOSEMITE ST - STE 900
 City: DENVER State: CO Zip: 80237-

Findings:

- 6 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Miller, Richard		r.miller@grynberg.com	All inspections
Pesicka, Conor		conor.pesicka@state.co.us	
Precup, Jim		james.precup@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
267624	WELL	SI	02/11/2015	DSPW	123-21426	CROISSANT 1	SI

General Comment:

(This area is intentionally left blank for general comments.)

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type WELLHEAD

Comment: Wire Panels

Corrective Action:

Date: _____

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
			CENTRALIZED BATTERY		
Comment:		Refer to location: 3178527			
Corrective Action:					Date: _____

Paint

Condition

Other (Content)

Other (Capacity)

Other (Type)

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date: _____

Venting:

Yes/No

Comment:

Corrective Action:

Date: _____

Flaring:

Type				
Comment:				
Corrective Action:				Date: _____

Inspected Facilities

Facility ID: 267624 Type: WELL API Number: 123-21426 Status: SI Insp. Status: SI

Underground Injection Control

UIC Violation: _____ Maximum Injection Pressure: _____

UIC Routine

Inj./Tube: Pressure or inches of Hg _____ Previous Test Pressure _____ MPP _____
 (e.g. 30 psig or -30" Hg) Inj Zone: LYNS

TC: Pressure or inches of Hg _____ Previous Test Pressure _____ Last MIT: 08/20/2014

Brhd: Pressure or inches of Hg _____ Previous Test Pressure _____ AnnMTReq: _____

Comment: _____

Corrective Action: _____ Date: _____

Method of Injection: PUMP FEED

Test Type: Verification of Repairs Tbg psi: _____ Csg psi: 500 BH psi: NA

Insp. Status: _____

Comment: Casing was pressurized to 500 PSI and held with no change for 15 Minutes.

Corrective Action: _____ Date: _____

BradenHead

Comment: Bradenhead remains below surface. Corrective action noted on previous inspection, document number: 684903832. Corrective action date remains from original citation.

Corrective Action: Plumb Bradenhead to Surface. Date: 07/05/2017

COGCC Comments

Comment	User	Date
<u>MIT Test Witness</u>	carlilec	03/01/2018
<u>Test Results</u>		
<u>11:30, Pressure 500 PSI</u>		
<u>11:35 Pressure 500 PSI</u>		
<u>11:40 Pressure 500 PSI</u>		
<u>11:45 Pressure 500 PSI</u>		
<u>Zero pressure gain or loss during test.</u>		
<u>Previous corrective action concerning exposing bradenhead remains with corrective action date of 7/7/17 from inspection document: 684903832.</u>		
<u>Operator plans to expose bradenhead at time of site remediation.</u>		

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401560079	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4390706
690001190	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4390704