

Inspection Photos

API: 05-007-06185

Operator: SOUTHLAND ROYALTY COMPANY

Inspection Date: 2/28/2018



Photo 1. View of the project area from the southwestern corner facing center.



Photo 2. View of the western portion of the project area from the southwestern corner facing northward. Revegetation is progressing with grasses such as intermediate wheatgrass (*Thinopyron intermedium*).



Photo 3. View of the southern portion of the project area from the southeastern corner facing westward. Kochia debris needs to be removed and properly disposed of.



Photo 4. View of the southern portion of the project area from the southeastern corner facing westward. Kochia debris needs to be removed and properly disposed of.