

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/05/2018

Submitted Date:

03/05/2018

Document Number:

689500628

FIELD INSPECTION FORM

Loc ID 316039 Inspector Name: GRANAHAN, KYLE On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 200502
Name of Operator: 31 OPERATING
Address: 3021 RIDGE RD #156
City: ROCKWALL State: TX Zip: 75032

Findings:

8 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

Contact Information:

| Contact Name | Phone | Email | Comment |
|---------------|--------------|-----------------------------|--------------------|
| , Sutherland | | msutherland@31operating.com | Rangely area wells |
| Freeman, Kris | 972-810-1031 | kfreeman@31operating.com | Rangely area wells |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 231968 | WELL | PR | 04/01/2014 | GW | 103-09639 | PUCKETT 34-8 | PR |

General Comment:

[On location to conduct routine inspection](#)

Location

Overall Good:

| | | | |
|----------------------|---|-------|--|
| Signs/Marker: | | | |
| Type | WELLHEAD | | |
| Comment: | Present/complete - previous operator information present at time of inspection. | | |
| Corrective Action: | | Date: | |
| Type | BATTERY | | |
| Comment: | Present/complete - previous operator information present at time of inspection. | | |
| Corrective Action: | | Date: | |

| | | | |
|---------------------------|---|-------|--|
| Emergency Contact Number: | | | |
| Comment: | Present/complete - previous operator information present at time of inspection.877-352-4660 | | |
| Corrective Action: | | Date: | |

Overall Good:

| | | | |
|--|------|--------|--|
| Spills: | | | |
| Type | Area | Volume | |
| In Containment: No | | | |
| Comment: | | | |
| <input type="checkbox"/> Multiple Spills and Releases? | | | |

| | | | |
|--------------------|----------|-------|--|
| Fencing/: | | | |
| Type | WELLHEAD | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

| | | | |
|-----------------------------------|-----|-------|-----------------|
| Equipment: | | | corrective date |
| Type: Gas Meter Run | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Deadman # & Marked | # 4 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Bird Protectors | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Horizontal Heated Separator | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

| | | | |
|--------------------|----|-------|--|
| Venting: | | | |
| Yes/No | NO | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

| | | | |
|--------------------|--|-------|--|
| Flaring: | | | |
| Type | | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Inspected Facilities

Facility ID: 231968 Type: WELL API Number: 103-09639 Status: PR Insp. Status: PR

Producing Well

Comment: [PR - via natural lift, no leaks/venting at time of inspection.](#)

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| | | Compaction | Pass | | | |
| | | Gravel | Pass | | | |
| Gravel | Pass | | | | | |
| Compaction | Pass | | | | | |

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|----------------------|---|
| 401563543 | INSPECTION SUBMITTED | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4393769 |
| 689500629 | Location | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4393757 |