

Environmental

Spills/Releases:

Type of Spill: PRODUCED WATER Estimated Spill Volume: 25

Comment: Followup to spill report of 3/5/18. Site is an injection well and tank battery. Weather clear and 23F. 2-3 inches partial snow cover. Tank overflow from 6x400 bbl, pw AST battery in poly-lined steel SPCC. No apparent leakage outside of containment. F-19 (closed) states that spill was 100% recovered and pumped back into tanks, however 3-4 inches of frozen, oily water remains pooled on the north side of SPCC containment.

Corrective Action: Pump all remaining water back into AST as soon as ice melts and water can be pumped. Follow-up with corrective action report. Date: 03/30/2018

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well Complaint:

DWR Receipt Num: _____ Owner Name: _____ GPS : _____ Lat _____ Long _____

Field Parameters:

Sample Location: _____ Comment: _____

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
690300220	Inspection photos 103-11603	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4399823