

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/26/2014

Submitted Date:

03/06/2018

Document Number:

680602519**FIELD INSPECTION FORM**
 Loc ID 440411 Inspector Name: ROY, CATHERINE On-Site Inspection ☐ 2A Doc Num:
Operator Information:OGCC Operator Number: 99999Name of Operator: OLD OPERATORS - STATUS UNKNOWNAddress: SEE COMMENT LINE IN WELLCity: XXXXXXX State: XX Zip: **Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:2 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
440410	WELL	TA	07/07/2015	OW	007-40037	Underwood Ditch 5	RI

General Comment:This location appeared to be leaking water. It was referred to Mark Weems on August 28, 2014.

Inspected FacilitiesFacility ID: 440410 Type: WELL API Number: 007-40037 Status: TA Insp. Status: RI**COGCC Comments**

Comment	User	Date
This is located at 37.04017, -106.84188. There appears to be two old wells in this location.	RoyC	03/06/2018

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401565410	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4395263
680602521	Inspection Photo	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4395259