

FORM  
INSPRev  
X/15

# State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/13/2018

Submitted Date:

03/13/2018

Document Number:

689300649

## FIELD INSPECTION FORM

|  |                                 |   |                   |   |
|--|---------------------------------|---|-------------------|---|
| Loc ID<br>334592   | Inspector Name:<br>Holtz, Darin | On-Site Inspection <input type="checkbox"/> | 2A Doc Num: _____ | <b>Status Summary:</b><br><input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION<br><input type="checkbox"/> FOLLOW UP INSPECTION REQUIRED<br><input checked="" type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED<br><br><b>Findings:</b><br>4 Number of Comments<br>1 Number of Corrective Actions<br><input checked="" type="checkbox"/> Corrective Action Response Requested |
| <b>Operator Information:</b><br>OGCC Operator Number: 10456<br>Name of Operator: CAERUS PICEANCE LLC<br>Address: 1001 17TH STREET #1600<br>City: DENVER State: CO Zip: 80202 |                                 |   |                   |   |

### Contact Information:

| Contact Name     | Phone         | Email                                 | Comment                  |
|------------------|---------------|---------------------------------------|--------------------------|
| Elsener, Garrett | (303)565-4600 | COGCC.inspections@caerusoilandgas.com | All Piceance inspections |
| ,                |               | dnr_COGCCEngineering@state.co.us      |                          |

### Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name         | Insp Status |
|-------------|------|--------|-------------|------------|-----------|-----------------------|-------------|
| 257132      | WELL | PR     | 01/30/2001  | GW         | 045-07518 | ROSE RANCH 14-6 (J14) | TA          |

### General Comment:

Onsite to witness MIT. Any outstanding CA's still apply.

**Location**Overall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: Overall Good: ☐**Spills:**

| Type | Area | Volume |  |  |
|------|------|--------|--|--|
|------|------|--------|--|--|

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

|                    |  |       |  |
|--------------------|--|-------|--|
| Yes/No             |  |       |  |
| Comment:           |  |       |  |
| Corrective Action: |  | Date: |  |

**Flaring:**

|                    |  |       |
|--------------------|--|-------|
| Type               |  |       |
| Comment:           |  |       |
| Corrective Action: |  | Date: |

**Inspected Facilities**Facility ID: 257132 Type: WELL API Number: 045-07518 Status: PR Insp. Status: TA**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: \_\_\_\_\_Comment: Rule 319b Temporary Abandonment.Corrective Action: No Form 4 on file for continued TA status.Date: 04/13/2018**Workover**Comment: 10 day MIT notification recieved, Document #401556033. D&B water services on site to perform test. Starting PSI- 350, 5 min-PSI 349, 10 min-PSI 349, Final PSI 349. PSI lose 1 psi.

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description                | URL   |
|--------------|----------------------------|---|
| 689300652    | 689300649 inspection photo | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4400164">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4400164</a> |