

Inspection Photos
Location Name: Dwinell 4
API: 05-057-05134



Photo 1. Overview of location taken at entrance facing southwest.

Inspection Photos
Location Name: Dwinell 4
API: 05-057-05134



Photo 2. Lube oil without containment and leaking at wellhead.



Photo 3. Knocked over container with no secondary containment.