

Inspection Photos
Location Name: Cody 1
API: 05-057-05135



Photo 1. Overview of location taken at entrance facing southeast.



Photo 2. 1 – 3" and 2 – 2" steel risers not marked or LO/TO.

Inspection Photos
Location Name: Cody 1
API: 05-057-05135



Photo 3. Incomplete tank label.



Photo 4. Incomplete tank label.

Inspection Photos
Location Name: Cody 1
API: 05-057-05135



Photo 5. 1 – 2" steel risers not marked or LO/TO.



Photo 6. Knocked over container with no secondary containment.

Inspection Photos
Location Name: Cody 1
API: 05-057-05135



Photo 7. Landfarm.



Photo 8. Landfarm.