

# Final Reclamation Inspection

March 7, 2018

Operator: EXTRACTION OIL & GAS INC - #10459

API: 05-123-11395

Inspection Document #: 682403377

Weld County, CO

NWNW Section 32 T1N R68W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos  
Location Name: HIPPEN #1-32  
API: 05-123-11395



Google Earth aerial imagery taken June 9, 2017, post plugging, illustrates equipment was left at the battery location at least eighteen months post plugging operations. Well was plugged 12/5/2015. See the following image for a close-up of the battery location.

Inspection Photos  
Location Name: HIPPEN #1-32  
API: 05-123-11395



Close-up Google Earth aerial imagery from the battery location taken June 9, 2017, post plugging, illustrates equipment was left at the battery location at least eighteen months post plugging operations. At the time of this inspection, an abandoned riser remains at the battery location- see Photos 7&8.



Inspection Photos  
Location Name: HIPPEN #1-32  
API: 05-123-11395



**Photo 1.** Photo taken from the approximate well location, facing West. No visual evidence of equipment on the well location. Appears the Operator has performed final reclamation activities. Undesirable weedy annual vegetation (Kochia) appears to be establishing throughout portions of the disturbance area. Germination of desirable vegetation did not appear uniform throughout the disturbance area. Operator may need to conduct additional reclamation activities.



**Photo 2.** Photo taken from the approximate well location, facing North. See comments under Photo 1.

Inspection Photos  
Location Name: HIPPEN #1-32  
API: 05-123-11395



**Photo 3.** Photo taken from the approximate well location, facing East. See comments under Photo 1.



**Photo 4.** Photo taken from the approximate well location, facing South. See comments under Photo 1.



Inspection Photos  
Location Name: HIPPEN #1-32  
API: 05-123-11395



**Photo 5.** Photo taken from the northeast well location, facing South. A patch of bare ground (~20'x~20') evident with no germination.



**Photo 6.** Reference photo taken south of the well location, facing South.

Inspection Photos  
Location Name: HIPPEN #1-32  
API: 05-123-11395



**Photo 7.** Photo taken from the western battery location, facing East. Operator has failed to remove an abandoned riser and failed to perform final reclamation activities.



**Photo 8.** Close-up photo taken of the abandoned riser. Riser was locked out/tagged out with an Extraction contact.