

Inspection Photos
Location Name: Haley-Ray #13-21
API: 05-123-22935



Photo 1: Looking SE at site location




Photo 2: wellhead looking N.



Inspection Photos
Location Name: Haley-Ray #13-21
API: 05-123-22935



Photo 3: stained soil at wellhead



Photo 4: Unused 2" plugged riser

Inspection Photos
Location Name: Haley-Ray #13-21
API: 05-123-22935



Photo 5: Water vault capacity not shown



Photo 6: Unused fittings

Inspection Photos
Location Name: Haley-Ray #13-21
API: 05-123-22935



Photo 7: Burrows in berm



Photo 8: Stormwater erosion on S. side of location