

Inspection Photos
Location Name: State 6-81-24-4
API: 05-057-06510



Photo 1. Overview of location taken at entrance facing west.

Inspection Photos
Location Name: State 6-81-24-4
API: 05-057-06510



Photo 2. Uncompacted berm.



Photo 3. Uncompacted berm.

Inspection Photos
Location Name: State 6-81-24-4
API: 05-057-06510



Photo 4. No wildlife protection apparent.



Photo 5. Open rat hole.

Inspection Photos
Location Name: State 6-81-24-4
API: 05-057-06510



Photo 6. No wellhead sign, concrete base and metal container stored on location.



Photo 7. Battery sign falling off post with incorrect well name.