

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/14/2018

Submitted Date:

03/15/2018

Document Number:

689100127

**FIELD INSPECTION FORM**

Loc ID 335672 Inspector Name: LUJAN, CARLOS On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10456  
Name of Operator: CAERUS PICEANCE LLC  
Address: 1001 17TH STREET #1600  
City: DENVER State: CO Zip: 80202

**Findings:**

- 7 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

**Contact Information:**

Contact Name	Phone	Email	Comment
Spencer, Stan		stan.spencer@state.co.us	EPS, NW Region
Middleton, Brett		bmiddleton@caerusoilandgas.com	Sr. Environmental Specialist
Fischer, Alex		alex.fischer@state.co.us	Environmental Supervisor, NW
Lujan, Carlos		carlos.lujan@state.co.us	EPS, NW Region
Janicek, Jake		JJanicek@caerusoilandgas.com	EHS Professional
McKee, Michael		MMckee@caerusoilandgas.com	EHS Manager

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
335672	LOCATION	AC			-	N.PARACHUTE-65S96W 23NWNW	EI

**General Comment:**

Inspection conducted in response to Caerus interest in using pad D23 on West Fork, North Pareachute to store and treat cuttings originated on the K10 pad. On site with Jake Janicek from Caerus. Sunny, temp around 60 oF. Distance from K10 to D23 is about a mile and a half, on the same West Fork road. Road is in good conditions. The location had two pits (#425558 and #455559) that were closed in accordance with COGCC Rules and Regulations, per REM #7749 and 7750. There are four producing wells and four AL wells at the center of the pad. Additional equipment include a separator and a meter house. No produced water or condensate tanks were observed on site. The pad is clean (no stainings) with no junk, stored equipment, or stock piled material. No vegetation growth on site. The pad is partially bermed. The distance from the pad to the creek is approximately 100 feet. The pad has a large unused surface that could be used to store and/or treat cuttings without interfering with normal operations. Proximity to surface water (and potentially a not too deep water table) are the main issues to be considered for cutting storage purposes (i.e. Storm water management, including berms and well compacted soil).

**Inspected Facilities**Facility ID: 335672 Type: LOCATION API Number: - Status: AC Insp. Status: EI**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689100128	View of D23 pad #1	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4404693">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4404693</a>
689100129	View of D23 pad #2	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4404694">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4404694</a>