

Inspection Photos

Location ID: 453917

Operator: BP PRODUCTION COMPANY

Inspection Date: 2/28/2018



Photo 1. View of the project area from the southeastern corner facing center. Tree clearing operations occurring at the time of the inspection.



Photo 2. View of the southern portion of the project area from the southeastern corner facing westward.



Photo 3. View of the southern portion of the project area from the southwestern corner facing eastward. Vegetation within the project area is largely comprised of sagebrush (*Artemisia tridentata*), juniper (*Juniperus* sp.), pinyon (*Pinus edulis*), wolfberry (*Lycium pallidum*), blue grama (*Bouteloua gracilis*), Prickly pear (*Opuntia* sp.), and cheatgrass (*Bromus tectorum*).



Photo 4. View of cattle pond northeast of the project area.