

Inspection Photos
Location Name: Clovis B #2
API: 05-067-08680



Black material near the southwest edge of location.



Photo looking north from unidentified spill area.

Inspection Photos
Location Name: Clovis B #2
API: 05-067-08680



Unidentified spill area.



Flow path from southwest corner of location toward the west.

Inspection Photos
Location Name: Clovis B #2
API: 05-067-08680



Terminus of flow path.



Old location sign remains on site.

Inspection Photos
Location Name: Clovis B #2
API: 05-067-08680



Landowner equipment in northeast corner of location.



Debris near entrance to location.