

**Inspection Photos**  
**Location Name: Payne-Schmitt #1**  
**API: 05-067-06814**



**Payne-Schmitt #1 well head and stained soil.**



**Location appears to have recently been dragged.**



**Inspection Photos**  
**Location Name: Payne-Schmitt #1**  
**API: 05-067-06814**



**Close up of fluids leaking from well head.**



**Drop out tank with gas supply line.**

**Inspection Photos**  
**Location Name: Payne-Schmitt #1**  
**API: 05-067-06814**



**55 gal. drums in secondary containment.**



**Stained, wet soil underneath prime mover.**



**Inspection Photos**  
**Location Name: Payne-Schmitt #1**  
**API: 05-067-06814**



**Alternate view of stained soil beneath prime mover.**



**Stained soil beneath tank load out valves.**



**Inspection Photos**  
**Location Name: Payne-Schmitt #1**  
**API: 05-067-06814**



**Stained soil beneath load out valve on eastern tank.**



**Stained soil beneath load out valve on western tank.**



**Inspection Photos**  
**Location Name: Payne-Schmitt #1**  
**API: 05-067-06814**



**Additional valve on western tank with stained soil.**



**Inadequate secondary containment berm capacity.**