

Inspection Photos  
Location Name: USA-Clark Millison 1  
API: 05-081-07006



**Photo 1. Overview of location taken at entrance facing northeast.**

Inspection Photos  
Location Name: USA-Clark Millison 1  
API: 05-081-07006



**Photo 2. No wildlife protection apparent on all exhaust.**



**Photo 3. Peeling tank label.**

Inspection Photos  
Location Name: USA-Clark Millison 1  
API: 05-081-07006



**Photo 4. No tank label.**



**Photo 5. Pit.**

Inspection Photos  
Location Name: USA-Clark Millison 1  
API: 05-081-07006



**Photo 6. Separator cluster. Unsure if all are in use.**



**Photo 7. Stained soil at separator.**

Inspection Photos  
Location Name: USA-Clark Millison 1  
API: 05-081-07006



**Photo 8. Separator. Unsure if in use.**



**Photo 9. No wellhead sign, tubing stored at wellhead.**

Inspection Photos  
Location Name: USA-Clark Millison 1  
API: 05-081-07006



**Photo 10. One of multiple areas of stored/unused equipment.**



**Photo 11. Second view of one of multiple areas of stored/unused equipment.**

Inspection Photos  
Location Name: USA-Clark Millison 1  
API: 05-081-07006



**Photo 12. Landfarm area.**



**Photo 13. Second of multiple areas of stored/unused equipment.**

Inspection Photos  
Location Name: USA-Clark Millison 1  
API: 05-081-07006



**Photo 14. Third of multiple areas of stored/unused equipment.**



**Photo 15. Unlabeled tank.**