

# Inspection Photos

API: 05-067-05436

Operator: FAULCONER INC\* VERNON E

Inspection Date: 3/7/2018



**Photo 1. View of the project area from the northwestern edge of the access road facing center. Tear drop is being revegetated.**





**Photo 2. View of the northwestern portion of the project area from the northwestern edge facing southward. Cut bank appears to be stabilized with perennial vegetation.**





**Photo 3. View of the eastern portion of the project area from the southeastern edge facing northward. Revegetation is progressing with grasses such as smooth brome (*Bromus inermis*) and sand dropseed (*Sporobolus cryptandrus*).**