

# Inspection Photos

API: 05-067-08146

Operator: SG INTERESTS I LTD

Inspection Date: 3/7/2018



**Photo 1. View of the project area from the northeastern corner facing center. Well pad is constructed and not reclaimed. Cut-slopes are evident.**





**Photo 2. View of the eastern portion of the well pad from the northeastern corner facing southward. Well pad fill-slopes are evident.**





**Photo 3. View of the southern portion of the project area from the southeastern corner facing westward. Soils are rocky with little vegetation. Fill is elevated from adjacent contour by approximately 10 to 12 feet.**





**Photo 4. View of the eastern portion of the project area from the southeastern edge facing northward.**





**Photo 5. View of reference area south of the well pad.**