

Inspection Photos
Location Name: Dowler #1A
API: 05-067-06406



Dowler #1A well head.



Below grade valve access and pig launcher.

Inspection Photos
Location Name: Dowler #1A
API: 05-067-06406



Chemical injection system on secondary containment.



Dowler #1B well head.

Inspection Photos
Location Name: Dowler #1A
API: 05-067-06406



**Well head packing was leaking during this field inspection.
Ice had formed on well head and production piping.**



Hilcorp representative replacing well head packing.

Inspection Photos
Location Name: Dowler #1A
API: 05-067-06406



Compression fitting removed to replace packing.



Worn out packing rings were allowing gas and fluids to escape.