

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type UNUSED EQUIPMENT

Comment: [Empty, unused, disconnected methanol barrel & pump at wellhead. See photos.](#)

Corrective Action: [Comply with 603.f](#)

Date: 04/13/2018

Overall Good:

Spills:

Type	Area	Volume

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type WELLHEAD

Comment: [Iron, Livestock have mangled fence. May want to set posts. See photos.](#)

Corrective Action:

Date: _____

Equipment:

Type: Plunger Lift

1

corrective date

Comment:

Corrective Action:

Date: _____

Venting:

Yes/No

Comment:

Corrective Action:

Date: _____

Flaring:

Type

Comment:

Corrective Action:

Date: _____

Inspected Facilities

Facility ID: 248974 Type: WELL API Number: 123-16776 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

COGCC Comments

Comment	User	Date
Well commingles at Battery (#435351) with UPRC 23-4A (123-16107) and Ferguson B23-19 (123-25075). All surface production equipment and tanks are identified on their inspection form, See DOC#69130035.	kraicha	03/14/2018

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401574937	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4403314
691300038	Inspection photo.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4403310