

Inspection Photos
Location Name: DF Ranch #17-34
Location ID: 302912



Photo 1: Location, looking NW



Photo 2: Wellhead, looking N

Inspection Photos
Location Name: DF Ranch #17-34
Location ID: 302912



Photo 3: Stained soil, residue at engine



Photo 4: Stained soil at wellhead

Inspection Photos
Location Name: DF Ranch #17-34
Location ID: 302912



Photo 5: Battery sign is inaccurate