

Inspection Photos
Location Name: Gallegos PC GJ #13-99HZ
Location ID: 417344



Photo 1: Location, looking SW



Photo 2: Wellhead, looking N

Inspection Photos
Location Name: Gallegos PC GJ #13-99HZ
Location ID: 417344



Photo 3: Stained soil at wellhead



Photo 4: Unused equipment on E side of pump jack

Inspection Photos
Location Name: Gallegos PC GJ #13-99HZ
Location ID: 417344



Photo 5: Unused equipment on W side of pump jack



Photo 6: Debris in treater house

Inspection Photos
Location Name: Gallegos PC GJ #13-99HZ
Location ID: 417344



Photo 7: Debris in treater house



Photo 8: Stained soil at engine

Inspection Photos
Location Name: Gallegos PC GJ #13-99HZ
Location ID: 417344



Photo 9: Stained soil at engine



Photo 10: Riser at pumpjack (E of wellhead)

Inspection Photos
Location Name: Gallegos PC GJ #13-99HZ
Location ID: 417344



Photo 11: Risers E of treater house.