

Inspection Photos
Location Name: Ray #07-20
Location ID: 332436



Photo 1: Location, looking SE



Photo 2: Wellhead, looking W



Inspection Photos
Location Name: Ray #07-20
Location ID: 332436



Photo 3: Stained soil at exhaust



Photo 4: Stained soil at engine

Inspection Photos
Location Name: Ray #07-20
Location ID: 332436




Photo 5: Riser, S of engine

