

**FORM
22**Rev
05/13**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

OGCC RECEPTION

Receive Date:
03/20/2018Accident Tracking No.:
401580601**ACCIDENT REPORT**

As required by Rule 602.b.

CONTACT INFORMATION☒ Initial Notice of Accident ☐ Subsequent Notice of Accident

OGCC Operator Number: 10261 Contact Name: Kevin Kane
Name of Operator: BAYSWATER EXPLORATION & PRODUCTION LLC Phone: (303) 893-2503
Address: 730 17TH ST STE 500 Fax: ()
City: DENVER State: CO Zip: 80202 Email: kkane@bayswater.us

DESCRIPTION OF ACCIDENT(Please be as specific as possible)

Date of Accident: 03/12/2018 Time of Accident: 7:45 AM
API Number: 05- 123-28010 Facility ID: _____ Type of Facility: WELL
Well/Facility Name: DYER Well/Facility Num: 2-24
County: WELD
Location: QTRQTR: SENW Sec: 2 Twp: 6N Rng: 64W Meridian: 6
Lat: 40.517650 Long: -104.518930
Field Name: HARLECH Field Number: 33560

DESCRIPTION

Provide a detailed description of the accident, problems, and cause (equipment failure, human error, etc.): actions taken to provide well control in detail::

At approximately 7:45-8:00 AM MDT, a contract farmer, while tractor plowing for the surface owner WELDCO Farms, collided with the Bayswater operated Dyer 2-24 wellhead causing a rupture to the piping at the south facing casing valve. It is not know why the wellhead was hit by the farmer as the wellhead was clearly marked with red fencing panels surrounding the well with a orange flag that extended significantly above the wellhead. The rupture resulted in an uncontrolled flow of the well to the atmosphere through the exposed south facing casing valve opening. The Galeton Fire District was dispatched to the well location. Bayswater personnel also were dispatched to the scene. The site situation was assessed. Weather conditions were clear with mild wind from the NE. Although the well flow was essentially contained within the plowed field, as a safety precaution, the owners of nearby residences to the south and west of the well location were notified. WCR 57 between WCR 72 and WCR 74 was closed to prevent traffic from traveling to south and west of the well flow. Well control experts were dispatched to the scene and arrived at approximately 3:00 PM MDT. After further assessing the situation, the well control contractor proceeded to replace the damaged casing valve and had the well shut in and controlled at approximately 4:00 PM MDT 3-12-2018. There were no personal injuries incurred as a result of this incident. Clean up and remediation operations were commenced immediately after well flow was shut in. A workover rig was moved in on 3-13-2018 to make necessary wellhead repairs. Soil clean up and remediation operations will continue until complete and are reported on COGCC Form 19.

OTHER NOTIFICATIONS

List the parties and agencies notified (LDG, County, BLM EPA, DOT, Local Emergency Planning Coordinator or others)

Date	Agency	Contact	Response
03/12/2018	Weld County	Troy Swain	Voicemail
03/12/2018	COGCC	John Axelson	Voicemail
03/12/2018	COGCC	Jim Preccup	Notified
03/12/2018	Public Works	Curtis Hall	Closed CR 57
03/12/2018	COGCC	Diana Burns	Notified

OPERATOR COMMENTS and SUBMITTAL

This form must be signed by an authorized agent of the entity making assertion.

I certify under penalty of perjury that this report has been examined by me and to the best of my knowledge is true, correct and complete.

Print Name: Kevin Kane

Email: kkane@bayswater.us

Signature:

Title:

Date: 03/20/2018

CONDITIONS OF APPROVAL, IF ANY:

COA Type	Description

General Comments

User Group	Comment	Comment Date
Information Systems	No subsequent report required.	03/21/2018

Total: 1 comment(s)

Attachment Check List

Att Doc Num	Name

Total Attach: 0 Files