

Inspection Photos

API# 071-06406

Operator: Timber Creek

Inspection Number: 680102758

Inspection Date: 3/7/2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:

Overview of Location to West. The Location, including well pad & access road, is not recontoured, decompacted, or revegetated.

March 7, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Timber Creek PA API#071-06406



Photo#2:
View Northeast along severely eroded fill slope.

March 7, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Timber Creek PA API#071-06406



Photo#3:

View of severe erosion leading top to base of fill slope.

March 7, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Timber Creek PA API#071-06406



Photo#4:

View of tree at base of fill slope whose root system has been undermined to point of collapse & entangled with silt fence that has become debris.

March 7, 2018



Photo#5:
Detail of silt fence debris along base of fill slope.

*

March 7, 2018



Photo#6:
Roof anchors, used as silt fence support still in place at base of fill slope.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Timber Creek PA API#071-06406



Photo#7:
Pipeline/ Drain? left on Southwest side of Location.

March 7, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Timber Creek PA API#071-06406



Photo#8:
Erosion is occurring on Access Rd.

March 7, 2018



Photo#9:
Refer to Photo#8 description.