

Construction and Stormwater Inspection

March 21, 2018

Operator: ENERPLUS RESOURCES (USA) CORPORATION - #10177

Location ID: 450827

Inspection Document #: 682403408

Weld County, CO

SWSE Section 26 T8N R67W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: IRISH PAD
Location ID: 450827



Photo 1. Photo taken from the entrance of location off CR 90 on February 27, 2018, facing South. Photo illustrates Operator sign.



Photo 2. Photo taken from the location entrance, facing North. Operator has installed a vehicle tracking device and appears to be in proper functioning condition.

Inspection Photos
Location Name: IRISH PAD
Location ID: 450827



Photo 3. Photo taken from the location entrance, facing North. Operator has installed culverts with a stabilized outlet in conjunction to the roadside ditch.



Photo 4. Photo taken from a portion of the access road, facing North. Operator has installed culverts with a stabilized outlet in conjunction to the roadside ditch, installed straw wattles, straw mulched and seeded the roadside ditch.

Inspection Photos
Location Name: IRISH PAD
Location ID: 450827



Photo 5. Photo taken from the approximate center of location, facing Northeast. Operator has installed and compacted gravel throughout the location.



Photo 6. Photo taken from the approximate center of location, facing South. See comments under Photo 5.

Inspection Photos
Location Name: IRISH PAD
Location ID: 450827



Photo 7. Photo taken from the western location, facing North. Operator has installed a moat system around the well pad perimeter. Fill and cut slopes have been seeded.



Photo 8. Photo taken from the western location, facing South. See comments under Photo 7.

Inspection Photos
Location Name: IRISH PAD
Location ID: 450827



Photo 9. Photo taken from the southern location on the topsoil stockpile, facing East. Operator has seeded portions of the topsoil stockpile for long-term stabilization and protection of topsoil, and installed erosion control blankets along the fill slope of the topsoil stockpile.



Photo 10. Photo taken from the southern location on the topsoil stockpile, facing East. See comments under Photo 9.