

Inspection Photos

API: 05-067-08776

Operator: BP AMERICA PRODUCTION COMPANY

Inspection Date: 3/7/2018



Photo 1. View of the project area from the southwestern corner facing center.



Photo 2. View of the western portion of the interim reclamation area from the northwestern corner facing westward. Revegetation is comprised of rubber rabbitbrush (*Chrysothamnus nauseosus*), smooth brome (*Bromus inermis*), and crested wheatgrass (*Agropyron cristatum*).



Photo 3. View of the southern portion of the project area from the southwestern corner facing eastward.



Photo 4. View of the northern portion of the project area from the northwestern corner facing eastward. Steep cut-slope supports sparse revegetation. This needs to be monitored and further slope stabilization measures taken if noticeable erosion is occurring.



Photo 5. View of trash barrel on south side of access road. Needs to be removed.