

# Inspection Photos

API: 05-067-08100

Operator: LOGOS OPERATING LLC

Inspection Date: 3/7/2018



**Photo 1. View of the project area from the western corner facing center.**





**Photo 2. View of the southwestern portion of the project area from the western corner facing southeastward. Revegetation is sparse and intensely grazed, not in identifiable form.**





**Photo 3. View of the northwestern portion of the project area from the western corner facing northeastward.**





**Photo 4. View of the southeastern portion of the project area from the southern edge facing northeastward.**